



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

January 6, 2010

Reviewed: PPB

Mine Name: B&C Limestone Quarry	Permit Number: M/039/0013
Operator Name: Bryce Haas	Inspection Date: November 5, 2009
Inspector(s): Lynn Kunzler, Brett Gregory	Time: 1:30 pm
Other Participants: none	Mine Status: Undergoing Reclamation

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check status of reclamation work.

Inspection Summary:

There has been no apparent reclamation work since my August visit. Photos were again taken from the water tank area for comparison to other inspection photos.

Conclusions and Recommendations:

After the several attempts to have this site reclaimed, and extending deadlines to complete the work only to have the operation still unreclaimed, the Division should consider proceedings to have the surety forfeited and proceed to contract the rest of the reclamation.

Continue to monitor this site when in the area.

Inspector's Signature

Cc: John Blake, SITLA
Bryce Haas, Operator

O:\M039-Sanpete\M0390013-BandCLimestone\inspections\insp-11052009.doc